

Hazardous Building Materials Inspection Report (Non-Destructive)

Former Hill Crest Country Club with Outbuildings
2200 Larpenteur Avenue East
Maplewood, Minnesota

Prepared for

Saint Paul Port Authority



May 16, 2019

Project B1903316

Mr. Monte Hilleman
Saint Paul Port Authority
380 St. Peter Street, Suite 850
Saint Paul, MN 55102

Re: Hazardous Building Materials Inspection Report (Non-Destructive)
Former Hill Crest Country Club and Outbuildings
2200 Larpenteur Avenue East
Maplewood, Minnesota

Dear Mr. Hilleman:

The enclosed report provides the results of the hazardous building materials inspection (non-destructive) conducted on May 2, 2019 at the former Hill Crest Country Club and outbuilding located at 2200 Larpenteur Avenue East in Maplewood, Minnesota (Site). Braun Intertec Corporation was authorized to conduct this inspection in accordance with our Proposal QTB097210 dated April 3, 2019 and our General Conditions.

The following outline provides the structure of the report.


- Scope of Services
- Site Description
- Results
- Discussion
- Limitations

If you have any questions or need further assistance, please call Jerry Wallerius at 952.995.2478 or Robert Nordby at 952.995.2424.

Sincerely,

BRAUN INTERTEC CORPORATION


Gerald J. Wallerius, CHMM
Project Scientist


Robert E. Nordby
Associate Principal – Senior Scientist

Attachments:

Hazardous Building Materials Inspection Report (Non-Destructive)
AA/EOF

Table of Contents

| Description | Page |
|--|------|
| A. Scope of Services | 1 |
| B. Site Description | 1 |
| C. Results | 2 |
| C.1. Asbestos | 2 |
| C.1.a. Asbestos-Containing Materials | 2 |
| C.1.b. Non-Asbestos-Containing Materials | 3 |
| C.2. Lead-Based Paint | 4 |
| C.3. Miscellaneous Regulated Waste | 5 |
| C.3.a. Mercury | 6 |
| C.3.b. Lead | 6 |
| C.3.c. Chlorofluorocarbons | 6 |
| C.3.d. Polychlorinated Biphenyl's | 6 |
| C.3.e. Electrical | 6 |
| C.3.f. Appliances | 6 |
| C.3.g. Oils | 6 |
| C.3.h. Miscellaneous | 6 |
| D. Discussion | 7 |
| D.1. Asbestos | 7 |
| D.1.a. Friable Asbestos-Containing Materials | 7 |
| D.1.b. Category I Non-Friable Asbestos-Containing Materials | 7 |
| D.1.c. Category II Non-Friable Asbestos-Containing Materials | 8 |
| D.2. Lead-Based Paint | 8 |
| D.3. Miscellaneous Regulated Waste | 8 |
| E. Limitations | 9 |
| F. Asbestos Inspector Certification | 9 |

Appendices

- A: Table I. Asbestos Building Inspection Results
- B: Table II. Bulk Asbestos Analytical Results
- C: Table III. Lead-Based Paint Testing Results
- D: Bulk Asbestos Laboratory Report and Chain of Custody Record
- E: Asbestos Inspector Certificate

A. Scope of Services

The scope of our services was limited to:

- Visually examine accessible areas and identify locations of suspect asbestos-containing materials (ACM), lead-based paint (LBP), polychlorinated biphenyls (PCBs), mercury, and other miscellaneous hazardous material.
- Collect and analyze representative bulk samples of materials suspected of containing asbestos.
- Conduct limited LBP testing of potential re-useable components with painted surfaces suspected of containing lead (where applicable). Testing will be accomplished using a Niton X-ray fluorescence (XRF) spectrum analyzer. The Niton is a portable, non-destructive, in-situ test and measurement instrument.
- Assign a hazard rating based on asbestos content with respect to the materials condition, friability, accessibility, and hazard potential.
- Document the various materials' current conditions and ACM quantities.
- Generate a final report documenting the sample locations, analysis results, conditions, and ACM quantities.

B. Site Description

The subject of the inspection is the former Hill Crest Country Club with outbuilding located at 2200 Larpenteur Avenue East in Maplewood, Minnesota (Site). The former Clubhouse building is a two-level structure constructed of mainly of wood, concrete slab and concrete block. It was constructed in 1999 and has an approximate footprint of 11,250 square feet. The typical interior finishes included sheetrock/joint compound, lay-in ceiling panels, stained wood beams/columns/wainscot, floor tile, ceramic tile, and carpeting. The typical exterior finishes included wood siding/soffits/fascia, concrete block, concrete decking, wood framed windows, metal and wood doors. The roofing materials consisted of asphalt shingles. The building was unoccupied at the time of this inspection.

The outbuilding included as part of the inspection were the pool house, NW parking lot garage, west storage building, north and south cart corral buildings, 1475 maintenance building, Haz Mat storage shed, maintenance building #2, maintenance garage #3, and well pump shed.

Note: At the time of the inspection, no access was available to the interior of the pool house, NW parking lot garage, west storage building, and north and south cart corral buildings.

C. Results

C.1. Asbestos

A total of forty-two (42) bulk samples were collected on May 2, 2019, and submitted to EMSL Analytical, Inc., a microscopy laboratory that is fully accredited for asbestos bulk analysis.

C.1.a. Asbestos-Containing Materials

The following is a summary of building materials found or assumed to contain greater than one percent asbestos (ACM by regulatory definition):

Former Clubhouse Building

- 12-inch by 12-inch ceiling tile (white), assumed due to sampling constraints
- 12-inch by 12-inch ceramic wall/floor tile (tan) with grout, assumed due to sampling constraints
- 1-inch by 1-inch ceramic floor tile (tan) with grout, assumed due to sampling constraints
- Asphalt shingles (brown) with tar paper, assumed due to sampling constraints
- Foundation waterproofing, assumed due to sampling constraints
- Wall panel adhesive, assumed due to sampling constraints

Pool House (Exterior Access Only)

- No suspect ACM observed at the time of the inspection

NW Parking Lot Garage (Exterior Access Only)

- No suspect ACM observed at the time of the inspection

West Storage Building (Exterior Access Only)

- No suspect ACM observed at the time of the inspection

North and South Cart Corral Buildings (Exterior Access Only)

- No suspect ACM observed at the time of the inspection

Debris pile on pavement between the Cart Corral Buildings

- 2-foot by 4-foot ceiling panel contains 4.25 percent (%) chrysotile (asbestos)

1475 Maintenance Building

- 12-inch by 12-inch floor tile (brown) contains 1.25% chrysotile

Haz Mat Storage Shed

- No suspect ACM observed at the time of the inspection

Maintenance Building #2

- No suspect ACM observed at the time of the inspection

Maintenance Garage #3

- Transit panels (gray) contains 25% chrysotile

Well Pump Shed

- No suspect ACM observed at the time of the inspection

C.1.b. Non-Asbestos-Containing Materials

The following is a summary of building materials found to contain no asbestos or materials that contain one percent or less asbestos (non-ACM by regulatory definition):

Former Clubhouse Building

- 12-inch by 12-inch ceramic floor tile (brown-gray) with grout
- 12-inch by 12-inch floor tile (tan) with adhesive (tan)
- 2-foot by 2-foot ceiling panels (textured, fissured, sheetrock)
- 2-foot by 4-foot ceiling panel (sheetrock)
- 4-inch by 4-inch ceramic floor tile (brown) with grout and adhesive (tan) and bedding
- Adhesive (tan) on plastic wall panel
- Adhesive (tan) under carpet
- Caulk (black) on doors and window frames
- Caulk (gray) on copper ledge
- Caulk (red) fire stop
- Caulk (tan) on siding
- Floor leveler (gray)
- Sheetrock/joint compound
- Vinyl base (beige) with adhesive (tan)

Pool House (Exterior Access Only)

- Asphalt shingles (gray) with tar paper
- Caulk (gray) on door frame
- Sealant (gray) on pool deck

NW Parking Lot Garage (Exterior Access Only)

- Asphalt shingles (gray, red, green) with tar paper
- Caulk (white) on garage door frame

West Storage Building (Exterior Access Only)

- Asphalt shingles (gray, red, green) with tar paper
- Caulk (white) on door frame
- Cellulose board

North and South Cart Corral Buildings (Exterior Access Only)

- Asphalt shingles (gray, red, green) with tar paper
- Cellulose board

Debris pile on pavement between the Cart Corral Buildings

- Sheetrock

1475 Maintenance Building

- 12-inch by 12-inch ceiling tile (fissured)
- 2-foot by 2-foot ceiling panel (pitted)
- Adhesive (tan) on wall panel
- Gasket (green, white)
- Sheetrock/joint compound

Haz Mat Storage Shed

- Asphalt shingles (black) with tar paper

Maintenance Building #2

- Asphalt shingles (gray) with tar paper
- Adhesive pucks (tan) on wall panel
- Cellulose board
- Sheetrock

Maintenance Garage #3

- Asphalt shingles (gray) with tar paper
- Cellulose board

Well Pump Shed

- 12-inch pipe gasket (white)
- Asphalt shingles (gray) with tar paper

Refer to Table I in Appendix A, which lists individual functional spaces of the building, the suspect materials identified in that functional space, whether the suspect material was identified by analysis to be ACM, an estimated amount of each suspect material for the functional space, material conditions, assessment categories, and hazard ratings based on subjective observations made by our representatives.

Refer to Table II in Appendix B, which lists the homogenous material sample numbers, sample locations, suspect material descriptions, and the analysis results for each sample. This table summarizes the results from the Bulk Asbestos Laboratory Reports, which is attached in Appendix D.

Bulk asbestos analysis was conducted in accordance with EPA Method 40 CFR, Chapter 1, Part 763, Subpart F, and Appendix A (7/1/87 Edition).

C.2. Lead-Based Paint

Testing of limited building components for LBP was accomplished utilizing a Niton XL XRF field portable analyzer, Model No. XLP703A - Serial No. 26139, equipped with a 40-milcurie CD-109 source - Serial No. TR3979, installed on May 15, 2017. Analysis decision-making protocols were based on compliance with the EPA and Minnesota Department of Health (MDH), which consider any XRF result of 1.0 milligram per square centimeter (mg/cm²) or greater to be LBP. The following is a list of LBPs that were found on the limited building components tested:

NW Parking Lot Garage (Exterior Access Only)

- Tan painted horizontal wood siding
- Tan painted wood soffits

West Storage Building (Exterior Access Only)

- Tan painted vertical wood siding
- Tan painted wood soffits and fascia

North and South Cart Corral Buildings (Exterior Access Only)

- Tan painted vertical and horizontal wood siding
- Tan painted wood soffits

Maintenance Building #2

- Tan painted wood soffit
- Tan painted wood window casing and sash
- Tan painted wood door frame
- White painted wood door
- White painted wood window casing and sash

Maintenance Garage #3

- Tan painted wood siding

The U.S. Occupational Safety and Health Administration (OSHA) Lead in Construction Standard 29 CFR 1926.62 applies to all situations where employees are engaged in the disturbance of lead-containing coatings, regardless of the quantity of lead involved. Therefore, any XRF result above 0.0 mg/cm² is considered “lead-containing coatings” in order to be in compliance with the OSHA standard. Demolition of the building may involve disturbing lead-containing coatings. Contractors should be informed of the presence of lead coatings and that they will be required to comply with the OSHA lead standard.

The following is a list of surfaces with lead-containing paint:

West Storage Building (Exterior Access Only)

- Tan painted horizontal wood siding
- Tan painted wood window frame and sill

North and South Cart Corral Buildings (Exterior Access Only)

- Tan painted wood fascia

Maintenance Building #2

- White painted steel beam

Maintenance Garage #3

- Tan painted wood garage door frame
- Tan painted wood window frame and sash

Refer to Table III in Appendix C, which lists the sample numbers, sample locations, component descriptions, XRF field results, and the paint condition for each sample.

C.3. Miscellaneous Regulated Waste

A visual inspection for miscellaneous regulated waste materials that require separate handling and disposal prior to disturbance during building demolition was also performed as part of this assessment. The following is a list of items documented at the Site:

C.3.a. Mercury

- Batteries – smoke detectors, emergency lighting systems, elevator control panels, exit signs, security systems and alarms
- Furnaces
- Lighting – fluorescent lamps, HID lamps
- Space heater controls
- Thermostats

C.3.b. Lead

- Exit signs
- Lead ring caps (roof vent pipe)
- Security systems

C.3.c. Chlorofluorocarbons

- Central air conditioning units
- Fire extinguishers
- Fire suppression system
- Refrigerators/freezers
- Walk-in cooler

C.3.d. Polychlorinated Biphenyl's

- Light ballasts
- Transformers

C.3.e. Electrical

- Electrical panels
- Fuses
- Motors and pumps
- Switch gears
- Transformers

C.3.f. Appliances

- Microwave oven
- Water heater

C.3.g. Oils

- Door closers
- Hydraulic fluid/Oil storage drums and containers
- Light ballasts

C.3.h. Miscellaneous

- Aerosol spray cans
- Circuit panels
- CO2 tanks for beverages
- Computer equipment
- Diesel fuel tank

- Electronic equipment
- Electronic thermostats
- Fungicides/Herbicides/Pesticides
- Gasoline tank
- Meters
- Miscellaneous cleaning supplies
- Overhead garage door openers
- Paint
- Pool chemicals
- Solid waste
- Stains
- Tires
- Treated timber

D. Discussion

D.1. Asbestos

D.1.a. Friable Asbestos-Containing Materials

The following ACMs are classified as friable materials according to EPA 40 CFR Part 61 National Emission Standard for Hazardous Air Pollutants (NESHAPs):

Former Clubhouse Building

- 12-inch by 12-inch ceiling tile (white), assumed due to sampling constraints

Debris pile on pavement between the Cart Corral Buildings

- 2-foot by 4-foot ceiling panels

The ACM ceiling panels located in the debris pile on the pavement between the cart corral buildings were observed to be in damaged condition and mixed with the other miscellaneous building debris. The ACM ceiling panels and associated debris should be removed and disposed of by a MDH Certified Asbestos Abatement Contractor. The remaining above friable ACMs were observed to be in good condition at the time of our inspection. These materials should be maintained in good condition to prevent potential exposure to asbestos. Friable ACMs are required to be removed prior to disturbance by renovation/demolition in accordance with applicable state and federal regulations.

D.1.b. Category I Non-Friable Asbestos-Containing Materials

The following ACM is classified as a Category I non-friable ACM according to EPA NESHAPs:

Former Clubhouse Building

- Asphalt shingles (brown) with tar paper –assumed due to sampling constraints

1475 Maintenance Building

- 12-inch by 12-inch floor tile (brown)

The above Category I non-friable ACM's were observed to be in good condition at the time of our inspection. These materials should be maintained in good condition to prevent potential exposure to asbestos. Category I non-friable ACMs are not considered a hazard unless cut, drilled, sanded, or otherwise abraded. However, any Category I material that may become friable during renovation/demolition must be removed prior to that activity. Secondly, if left in place, the crushing or recycling of demolition debris is strictly prohibited. In addition, all demolition debris containing Category I materials must be disposed of at a landfill specifically permitted to accept this type of waste.

D.1.c. Category II Non-Friable Asbestos-Containing Materials

The following ACM is classified as a Category II non-friable ACM according to EPA NESHAPs:

Former Clubhouse Building

- 12-inch by 12-inch ceramic wall/floor tile (tan) with grout, assumed due to sampling constraints
- 1-inch by 1-inch ceramic floor tile (tan) with grout, assumed due to sampling constraints
- Foundation waterproofing, assumed due to sampling constraints
- Wall panel adhesive, assumed due to sampling constraints

Maintenance Garage #3

- Transite panels (gray)

The above Category II non-friable ACMs were observed to be in good condition at the time of our inspection. These materials should be maintained in good condition to prevent potential exposure to asbestos. Category II non-friable ACMs are not considered a hazard unless cut, drilled, sanded, or otherwise abraded. However, Category II non-friable ACMs that may become friable during renovation/demolition must be removed prior to that activity.

D.2. Lead-Based Paint

Building components with LBP should be maintained in good condition. If the building were to be demolished in its entirety, building components with lead paint are not required to be removed or disposed of as lead or hazardous waste. Any LBP-containing demolition waste and/or debris generated during building demolition should be subject to proper handling and disposal, consistent with applicable regulations and requirements.

D.3. Miscellaneous Regulated Waste

In the case of building demolition, any of the miscellaneous regulated waste items listed in Section C.3 that will be disturbed, must be removed prior to disturbance and must be recycled or disposed of in accordance with state and federal guidelines.

E. Limitations

This inspection was limited to areas available for observation via non-destructive means. In any building, the potential exists for hazardous building materials to be located inside walls, above ceilings, under floors, and other inaccessible areas. Braun Intertec cannot be held responsible for the presence of any such hidden materials. In the case of building renovation/demolition, contractors involved in the project should be made aware of this potential. If previously unidentified suspect hazardous building materials are exposed during their activities they should be sampled and analyzed for content prior to any disturbance.


Note: A destructive ACM investigation is required by the MPCA prior to building demolition. In addition, access to the to the interior of the pool house, NW parking lot garage, west storage building, and north and south cart corral buildings will be required.

In performing its services, Braun Intertec used that degree of care and skill ordinarily exercised under similar circumstances by reputable members of its profession currently practicing in the same locality. No warranty, express or implied, is made.

F. Asbestos Inspector Certification

I, the undersigned, do hereby certify that I am an accredited Asbestos Inspector in the State of Minnesota. A photocopy of my current asbestos inspector certificate is attached in Appendix E.

Signature:  Date: May 16, 2019
Stephen A. Luth
Project Scientist
Minnesota Department of Health Asbestos Inspector No: AI10702

Signature:  Date: May 16, 2019
Gerald J. Wallerius, CHMM
Project Scientist
Minnesota Department of Health Asbestos Inspector No: AI2305

Appendix A

Table I. Asbestos Building Inspection Results

Client: St. Paul Port Authority

Location: Former Clubhouse with Outbuildings, 2200 Larpenteur Avenue E, Maplewood, Minnesota

Date of Inspection: May 2, 2019

Project: B1903316

Table I. Asbestos Building Inspection Results

| Functional Space | Homogeneous Material Description | Contains Asbestos (Yes/No) | Ref. Client Sample No. (See Table II) | Estimated Quantity Units | Material Condition ¹ | Hazard Category ² |
|---|--|----------------------------|---------------------------------------|--------------------------|---------------------------------|------------------------------|
| Lower Level- Mechanical Room | Sheetrock/joint compound | No | 1 | Not Quantified | ND | 0 |
| Lower Level- Mechanical Room | Furnace tape (black) tarry | No | 2 | <1 ft ² | ND | 0 |
| Lower Level- All Areas | Adhesive (tan) on carpet | No | 3 | 9,000 ft ² | ND | 0 |
| Lower Level- All Areas | Sheetrock/joint compound | No | 1 | Not Quantified | ND | 0 |
| Lower Level- Conference Room | 2-foot x 2-foot Ceiling panels (textured) | No | 4 | 160 ft ² | ND | 0 |
| Lower Level- Swing Room | 2-foot x 2-foot Ceiling panels (textured) | No | 4 | 160 ft ² | ND | 0 |
| Lower Level- Swing Room | 2-foot x 2-foot Ceiling panels (fissured) | No | 5 | 240 ft ² | ND | 0 |
| Lower Level- Swing Room | Vinyl base (beige) with adhesive (tan) | No | 6 | 100 lin. ft | ND | 0 |
| Lower Level- Club Room | 2-foot x 2-foot Ceiling panels (textured) | No | 4 | 900 ft ² | ND | 0 |
| Lower Level- Club Room | Caulk - fire stop (red) | No | 7 | 32 lin. ft | ND | 0 |
| Lower Level- Club Room | 12-inch x 12-inch Floor tile (tan) with adhesive (tan) | No | 8 | 350 ft ² | ND | 0 |
| Lower Level- Club Room | Vinyl base (beige) with adhesive (tan) | No | 6 | 80 lin. ft | ND | 0 |
| Lower Level- Caddy Shack | Sheetrock/joint compound | No | 1 | Not Quantified | ND | 0 |
| Lower Level- Caddy Shack | Vinyl base (beige) with adhesive (tan) | No | 6 | 40 lin. ft | ND | 0 |
| Lower Level- Conference Room, Laundry Room, Women's Locker Room | 2-foot x 2-foot Ceiling panels (textured) | No | 4 | 2,182 ft ² | ND | 0 |
| Lower Level- Laundry Room | 12-inch x 12-inch Floor tile (tan) with adhesive (tan) | No | 8 | 320 ft ² | ND | 0 |
| Lower Level- Laundry Room | Vinyl base (beige) with adhesive (tan) | No | 6 | 80 lin. ft | ND | 0 |
| Lower Level- Laundry Room | Caulk - (red) fire stop | No | 7 | 30 lin. ft | ND | 0 |
| Lower Level- Women's Locker Room | 12-inch x 12-inch Ceramic wall/floor tile (tan) with grout | Assumed | No Sample | 1,500 ft ² | ND | 1 |
| Lower Level- Women's Locker Room | 1-inch x 1-inch Ceramic floor tile (tan) with grout | Assumed | No Sample | 200 ft ² | ND | 1 |

Table I. Asbestos Building Inspection Results
2200 Larpenteur Avenue E, Maplewood, Minnesota
Project B1903316
Page 2

| Functional Space | Homogeneous Material Description | Contains Asbestos (Yes/No) | Ref. Client Sample No. (See Table II) | Estimated Quantity Units | Material Condition ¹ | Hazard Category ² |
|--------------------------------|---|----------------------------|---------------------------------------|--------------------------|---------------------------------|------------------------------|
| Lower Level- Men's Locker Room | 12-inch x 12-inch Ceramic wall/floor tile (tan) with grout | Assumed | No Sample | 1,600 ft ² | ND | 1 |
| Lower Level- Men's Locker Room | 1-inch x 1-inch Ceramic floor tile (tan) with grout | Assumed | No Sample | 240 ft ² | ND | 1 |
| Lower Level- Beverage Station | Adhesive (tan) on plastic wall panel | No | 9 | 800 ft ² | ND | 0 |
| Lower Level- Beverage Station | 2-foot x 2-foot Ceiling panel (sheetrock) | No | 10 | 225 ft ² | ND | 0 |
| Lower Level- Beverage Station | 4-inch x 4-inch Ceramic floor tile (brown) with grout, adhesive (tan) and bedding | No | 11 | 300 ft ² | ND | 0 |
| Upper Level- Kitchen | 2-foot x 4-foot Ceiling panel (sheetrock) | No | 12 | 2,500 ft ² | ND | 0 |
| Upper Level- Kitchen | 4-inch x 4-inch Ceramic floor tile (brown) with grout, adhesive (tan) and bedding | No | 11 | 3,100 ft ² | ND | 0 |
| Upper Level- Kitchen | Adhesive (tan) on plastic wall panel | No | 9 | 5,000 ft ² | ND | 0 |
| Upper Level- Kitchen | Sheetrock/joint compound | No | 1 | Not Quantified | ND | 0 |
| Upper Level- Bar & Entry | 12-inch x 12-inch Ceramic floor tile (brown-gray) with grout | No | 13 | 140 ft ² | ND | 0 |
| Upper Level- Bar | 4-inch x 4-inch Ceramic floor tile (brown) with grout, adhesive (tan) and bedding | No | 11 | 200 ft ² | ND | 0 |
| Upper Level- Bar | 2-foot x 2-foot Ceiling panel (sheetrock) | No | 10 | 200 ft ² | ND | 0 |
| Upper Level- Janitor's Closet | 2-foot x 4-foot Ceiling panel (sheetrock) | No | 12 | 100 ft ² | ND | 0 |
| Upper Level- All Areas | Sheetrock/joint compound | No | 15 | Not Quantified | ND | 0 |
| Upper Level- All Areas | Adhesive (tan) under carpet with floor leveler (gray) | No | 14 | 6,000 ft ² | ND | 0 |
| Upper Level- Dining Areas | 12-inch x 12-inch Ceiling tile (white) | Assumed | No Sample | 1,900 ft ² | ND | 1 |
| Upper Level- Restrooms (3) | 12-inch x 12-inch Ceramic wall/floor tile (tan) with grout | Assumed | No Sample | 1,700 ft ² | ND | 1 |
| Upper Level- All Areas | Adhesive on wall panel | Assumed | No Sample | Not Quantified | ND | 1 |

| Functional Space | Homogeneous Material Description | Contains Asbestos (Yes/No) | Ref. Client Sample No. (See Table II) | Estimated Quantity Units | Material Condition ¹ | Hazard Category ² |
|--|--|----------------------------|---------------------------------------|------------------------------|---------------------------------|------------------------------|
| Exterior- Front North | Caulk (tan) on siding | No | 16 | Not Quantified | ND | 0 |
| Exterior- Front North | Caulk (black) on doors and window frames | No | 17 | Not Quantified | ND | 0 |
| Exterior- Front North | Caulk (gray) on copper ledge | No | 18 | Not Quantified | ND | 0 |
| Exterior- Foundation | Foundation waterproofing | Assumed | No Sample | Not Quantified | ND | 1 |
| Exterior- Roof | Asphalt shingles (brown) with tar paper | Assumed | No Sample | 15,000 ft² | ND | 1 |
| Pool House- Exterior | Asphalt shingles (gray) with tar paper | No | 19 | 800 ft ² | ND | 0 |
| Pool House- Exterior | caulk (gray) on door frame | No | 20 | 50 lin. ft | ND | 0 |
| Pool House- Exterior | Sealant (gray) on pool deck | No | 21 | 75 lin. ft | ND | 0 |
| Northwest Parking Lot Garage- Exterior | Asphalt shingles (gray, red, green) with tar paper | No | 22 | 400 ft ² | ND | 0 |
| Northwest Parking Lot Garage- Exterior | Caulk (white) on garage door frame | No | 23 | 30 lin. ft | ND | 0 |
| West Storage Building- Exterior | Asphalt shingles (gray, red, green) with tar paper | No | 22 | 700 ft ² | ND | 0 |
| West Storage Building- Exterior | Caulk (white) on garage door frame | No | 23 | 15 lin. ft | ND | 0 |
| West Storage Building- Exterior | Cellulose board | No | 24 | 800 ft ² | ND | 0 |
| North Cart Corral- Exterior | Asphalt shingles (gray, red, green) with tar paper | No | 22 | 2,000 ft ² | ND | 0 |
| North Cart Corral- Exterior | Cellulose board | No | 24 | 1,600 ft ² | ND | 0 |
| South Cart Corral- Exterior | Cellulose board | No | 24 | 1,600 ft ² | ND | 0 |
| South Cart Corral- Exterior | Asphalt shingles (gray, red, green) with tar paper | No | 22 | 2,000 ft ² | ND | 0 |
| Debris Pile - On Pavement between Cart Corral Buildings | 2-foot x 4-foot Ceiling panel (fissured) | Yes | 25 | 20 ft² | D | 3 |
| Debris Pile - On Pavement | Sheetrock | No | 26 | 20 ft ² | ND | 0 |
| 1475 Maintenance Building- Interior | Sheetrock/joint compound | No | 27 | 3,500 ft ² | ND | 0 |
| 1475 Maintenance Building- Interior | 2-foot x 2-foot Ceiling panel (pitted) | No | 28 | 150 ft ² | ND | 0 |
| 1475 Maintenance Building- Interior | 12-inch x 12-inch Ceiling tile (fissured) | No | 29 | 150 ft ² | ND | 0 |

| Functional Space | Homogeneous Material Description | Contains Asbestos (Yes/No) | Ref. Client Sample No. (See Table II) | Estimated Quantity Units | Material Condition ¹ | Hazard Category ² |
|--|---|------------------------------|---------------------------------------|---------------------------|---------------------------------|------------------------------|
| 1475 Maintenance Building- Interior | 12-inch x 12-inch Floor tile (brown) with mastic (black) | Yes (Floor Tile Only) | 30 | 150 ft² | ND | 1 |
| 1475 Maintenance Building- Interior | Adhesive (tan) on wall panel | No | 31 | 150 ft ² | ND | 0 |
| 1475 Maintenance Building- Interior | Gasket (green) | No | 32 | 2 each | ND | 0 |
| 1475 Maintenance Building- Interior | Gasket (white) | No | 33 | 2 each | ND | 0 |
| Haz Mat Storage Shed- Roof | Asphalt shingles (black) with tar paper | No | 34 | 100 ft ² | ND | 0 |
| Maintenance Building #2- Exterior | Asphalt shingles (gray) with tar paper | No | 35 | 3,000 ft ² | ND | 0 |
| Maintenance Building #2- Exterior | Adhesive pucks (tan) on wall | No | 36 | 5 ft ² | ND | 0 |
| Maintenance Building #2- Interior | Sheetrock | No | 37 | 900 ft ² | ND | 0 |
| Maintenance Building #2- Interior | Cellulose board | No | 38 | 10 ft ² | ND | 0 |
| Maintenance Garage #3- Exterior | Asphalt shingles (gray) with tar paper | No | 35 | 700 ft ² | ND | 0 |
| Maintenance Garage #3- Interior | Transite (gray) | Yes | 39 | 120 ft² | ND | 1 |
| Maintenance Garage #3- Interior | Cellulose board | No | 40 | 1,200 ft ² | ND | 0 |
| Well Pump Shed- Exterior | 12-inch pipe gasket (white) | No | 41 | 1 each | ND | 0 |
| Well Pump Shed- Exterior | Asphalt shingles (gray) with tar paper | No | 42 | 200 ft ² | ND | 0 |

1. Condition of ACM:

ND = Not Damaged

D = Damaged

SD = Significantly Damaged

2. Hazard Category:

0 = No hazard - material does not contain asbestos

1 = ACM with potential for damage

2 = ACM with potential for significant damage

3 = Damaged or significantly damaged asbestos-containing miscellaneous material

4 = Damaged or significantly damaged friable asbestos-containing thermal system insulation

5 = Damaged or significantly damaged friable asbestos-containing surfacing material

Appendix B

Table II. Bulk Asbestos Analytical Results

Table II. Bulk Asbestos Analytical Results

Client: St. Paul Port Authority

Location: Former Clubhouse with Outbuildings, 2200 Larpenteur Avenue E, Maplewood, Minnesota

Date of Inspection: May 2, 2019

Project: B1903316

| Sample No. | Sample Location | | | Material | Asbestos Content (%) ¹ |
|------------|-----------------------|------------------|------------------|---|-----------------------------------|
| 1 | Clubhouse Bldg. | Lower Level | Mechanical Room | Sheetrock/joint compound | ND ² |
| 2 | Clubhouse Bldg. | Lower Level | Mechanical Room | Furnace tape (black) tarry | ND |
| 3 | Clubhouse Bldg. | Lower Level | Hallway | Adhesive (tan) on carpet | ND |
| 4 | Clubhouse Bldg. | Lower Level | Conference Room | 2-foot x 2-foot Ceiling panels (textured) | ND |
| 5 | Clubhouse Bldg. | Lower Level | Swing Room | 2-foot x 2-foot Ceiling panels (fissured) | ND |
| 6 | Clubhouse Bldg. | Lower Level | Swing Room | Vinyl base (beige) with adhesive (tan) | ND |
| 7 | Clubhouse Bldg. | Lower Level | Club Room | Caulk (red) fire stop | ND |
| 8 | Clubhouse Bldg. | Lower Level | Club Room | 12-inch x 12-inch Floor tile (tan) with adhesive (tan) | ND |
| 9 | Clubhouse Bldg. | Lower Level | Beverage Station | Adhesive (tan) on plastic wall panel | ND |
| 10 | Clubhouse Bldg. | Lower Level | Beverage Station | 2-foot x 2-foot Ceiling panel (sheetrock) | ND |
| 11 | Clubhouse Bldg. | Lower Level | Beverage Station | 4-inch x 4-inch Ceramic floor tile (brown) with grout, adhesive (tan) and bedding | ND |
| 12 | Clubhouse Bldg. | Upper Level | Kitchen | 2-foot x 4-foot Ceiling panel (sheetrock) | ND |
| 13 | Clubhouse Bldg. | Upper Level | Bar | 12-inch x 12-inch Ceramic floor tile (brown-gray) with grout | ND |
| 14 | Clubhouse Bldg. | Upper Level | Main Dining | Adhesive (tan) under carpet with floor leveler (gray) | ND |
| 15 | Clubhouse Bldg. | Upper Level | Janitor's Closet | Sheetrock/joint compound | ND |
| 16 | Clubhouse Bldg. | Exterior - Front | North | Caulk (tan) on siding | ND |
| 17 | Clubhouse Bldg. | Exterior - Front | North | Caulk (black) on doors and window frames | ND |
| 18 | Clubhouse Bldg. | Exterior - Front | North | Caulk (gray) on copper ledge | ND |
| 19 | Pool House | Exterior | North | Asphalt shingles (gray) with tar paper | ND |
| 20 | Pool House | Exterior | North | Caulk (gray) on door frame | ND |
| 21 | Pool House | Exterior | North | Sealant (gray) on pool deck | ND |
| 22 | NW Parking Lot Garage | Exterior | Northwest | Asphalt shingles (gray, red, green) with tar paper | ND |
| 23 | NW Parking Lot Garage | Exterior | Northwest | Caulk (white) on garage door frame | ND |

| Sample No. | Sample Location | | | Material | Asbestos Content (%) ¹ | | |
|------------|--------------------------------|-------------|----------------------|--|-----------------------------------|------------|------|
| 24 | West Storage Building | Exterior | West | Cellulose board | ND | | |
| 25 | Debris Pile | On Pavement | Between cart corrals | 2-foot x 4-foot Ceiling panel (fissured) | Ceiling Tile: | Chrysotile | 4.25 |
| 26 | Debris Pile | On Pavement | Between cart corrals | Sheetrock | ND | | |
| 27 | 1475 Maintenance Building | Interior | | Sheetrock/joint compound | ND | | |
| 28 | 1475 Maintenance Building | Interior | | 2-foot x 2-foot Ceiling panel (pitted) | ND | | |
| 29 | 1475 Maintenance Building | Interior | | 12-inch x 12-inch Ceiling tile (fissured) | ND | | |
| 30 | 1475 Maintenance Building | Interior | | 12-inch x 12-inch Floor tile (brown) with mastic (black) | Floor Tile: | Chrysotile | 1.25 |
| | | | | | Mastic: | N.D. | |
| 31 | 1475 Maintenance Building | Interior | | Adhesive (tan) on wall panel | ND | | |
| 32 | 1475 Maintenance Building | Interior | | Gasket (green) | ND | | |
| 33 | 1475 Maintenance Building | Interior | | Gasket (white) | ND | | |
| 34 | Haz Mat Storage Building | Roof | | Asphalt shingles (black) with tar paper | ND | | |
| 35 | Maintenance Building #2 | Roof | | Asphalt shingles (gray) with tar paper | ND | | |
| 36 | Maintenance Building #2 | Exterior | | Adhesive pucks (tan) on wall | ND | | |
| 37 | Maintenance Building #2 | Interior | | Sheetrock | ND | | |
| 38 | Maintenance Building #2 | Interior | | Cellulose board | ND | | |
| 39 | Maintenance Building Garage #3 | Interior | | Transite (gray) | Transite: | Chrysotile | 25 |
| 40 | Maintenance Building Garage #3 | Interior | | Cellulose board | ND | | |
| 41 | Well Pump Shed | Exterior | | 12-inch pipe (white) | ND | | |
| 42 | Well Pump Shed | Exterior | | Asphalt shingles (gray) with tar paper | ND | | |

* Materials containing 1 percent of asbestos or less are not considered to be asbestos-containing materials by the U.S.EPA.

1. Asbestos content is indicated as an approximate percent by area.

2. ND = None Detected

Appendix C

Table III. Lead-Based Paint Testing Results

Table III. Lead-Based Paint Testing

| Sample I.D. No. | Room/Area | | Component Description | | | Results | Paint Condition G = Good P = Peeling |
|-----------------|------------------------------|-----------------|---------------------------|-------------|------------|-------------|--|
| 1 | Calibration | | Surface | | | 1.00 | --- |
| 2 | Calibration | | Buried | | | 0.90 | --- |
| 3 | Calibration | | Surface | | | 0.90 | --- |
| 4 | NW Parking Lot Garage | Exterior | Siding- Vertical | Wood | Tan | 0.00 | P |
| 5 | NW Parking Lot Garage | Exterior | Soffit | Wood | Tan | 1.60 | P |
| 6 | NW Parking Lot Garage | Exterior | Fascia | Wood | Tan | 0.00 | P |
| 7 | NW Parking Lot Garage | Exterior | Garage Door Frame | Wood | Tan | 0.00 | P |
| 8 | NW Parking Lot Garage | Exterior | Siding- Horizontal | Wood | Tan | 3.30 | P |
| 9 | West Storage | Exterior | Siding- Horizontal | Wood | Tan | 0.60 | P |
| 10 | West Storage | Exterior | Siding- Horizontal | Wood | Tan | 0.80 | P |
| 11 | West Storage | Exterior | Siding- Vertical | Wood | Tan | 1.10 | P |
| 12 | West Storage | Exterior | Soffit | Wood | Tan | 1.80 | P |
| 13 | West Storage | Exterior | Fascia | Wood | Tan | 1.60 | P |
| 14 | West Storage | Exterior | Door Frame | Wood | Tan | 0.00 | P |
| 15 | West Storage | Exterior | Door | Wood | Tan | 0.00 | P |
| 16 | West Storage | Exterior | Window Frame | Wood | Tan | 0.70 | P |
| 17 | West Storage | Exterior | Window Sill | Wood | Tan | 0.10 | P |
| 18 | North Cart Corral | Exterior | Siding- Horizontal | Wood | Tan | 1.90 | P |
| 19 | North Cart Corral | Exterior | Siding- Vertical | Wood | Tan | 0.00 | P |
| 20 | North Cart Corral | Exterior | Soffit | Wood | Tan | 0.00 | P |
| 21 | North Cart Corral | Exterior | Fascia | Wood | Tan | 0.10 | P |
| 22 | North Cart Corral | Exterior | Siding- Vertical (West) | Wood | Tan | 0.00 | P |
| 23 | South Cart Corral | Exterior | Siding | Wood | Tan | 0.00 | P |
| 24 | South Cart Corral | Exterior | Siding- Vertical | Wood | Tan | 1.60 | P |
| 25 | South Cart Corral | Exterior | Fascia | Wood | Tan | 0.40 | P |
| 26 | South Cart Corral | Exterior | Soffit | Wood | Tan | 2.10 | P |
| 27 | Fence | Exterior | Fence | Wood | Tan | 0.00 | P |

Table III. Lead-Based Paint Testing
2200 Larpenteur Avenue E, Maplewood, Minnesota
Project B1903316
Page 2

| Sample I.D. No. | Room/Area | | Component Description | | | Results | Paint Condition G = Good P = Peeling |
|--------------------|---------------------------|----------|-----------------------|--------------|-------|---------|---|
| 28 | South Cart Corral | Exterior | Garage Door Frame | Wood | Tan | 0.00 | P |
| 29 | 1475 Maintenance Building | Interior | Wall | Sheetrock | White | 0.00 | P |
| 30 | 1475 Maintenance Building | Interior | Door | Wood | Tan | 0.00 | G |
| 31 | 1475 Maintenance Building | Interior | Door Frame | Wood | Tan | 0.00 | G |
| 32 | 1475 Maintenance Building | Exterior | Siding | Metal | Tan | 0.00 | G |
| 33 | 1475 Maintenance Building | Exterior | Overhead Door | Wood | Tan | 0.00 | G |
| 34 | 1475 Maintenance Building | Exterior | Door Frame | Metal | Tan | 0.00 | G |
| 35 | 1475 Maintenance Building | Exterior | Diesel Tank | Metal | Green | 0.00 | G |
| 36 | 1475 Maintenance Building | Exterior | Gasoline Tank | Metal | White | 0.00 | G |
| 37 | 1475 Maintenance Building | Exterior | Post | Metal | Brown | 0.00 | G |
| 38 | Haz Mat Storage | Exterior | Siding | Wood | Tan | 0.00 | G |
| 39 | Haz Mat Storage | Exterior | Soffit | Wood | Tan | 0.00 | G |
| 40 | Haz Mat Storage | Exterior | Fascia | Wood | Tan | 0.00 | G |
| 41 | Maintenance Building #2 | Exterior | Wall | Cement Block | Tan | 0.00 | P |
| 42 | Maintenance Building #2 | Exterior | Window Casing | Wood | Tan | 1.20 | P |
| 43 | Maintenance Building #2 | Exterior | Window Sash | Wood | Tan | 1.30 | P |
| 44 | Maintenance Building #2 | Exterior | Door Frame | Wood | Tan | 1.90 | P |
| 45 | Maintenance Building #2 | Exterior | Soffit | Wood | Tan | 2.90 | P |
| 46 | Maintenance Building #2 | Exterior | Fascia | Wood | Tan | 0.00 | P |
| 47 | Maintenance Building #2 | Interior | Wall | Cement Block | White | 0.00 | G |
| 48 | Maintenance Building #2 | Interior | Ceiling | Sheetrock | White | 0.00 | G |
| 49 | Maintenance Building #2 | Interior | Beam | Steel | White | 0.10 | G |
| 50 | Maintenance Building #2 | Interior | Column | Steel | White | 0.00 | G |
| 51 | Maintenance Building #2 | Interior | Window Casing | Wood | White | 1.60 | G |
| 52 | Maintenance Building #2 | Interior | Window Sash | Wood | White | 1.60 | G |
| 53 | Maintenance Building #2 | Interior | Door | Wood | White | 2.20 | G |
| 54 | Maintenance Garage #3 | Exterior | Siding | Wood | Tan | 1.80 | P |
| 55 | Maintenance Garage #3 | Exterior | Garage Door Frame | Wood | Tan | 0.50 | P |
| 56 | Maintenance Garage #3 | Exterior | Garage Door | Wood | Tan | 0.00 | P |
| 57 | Maintenance Garage #3 | Exterior | Window Frame | Wood | Tan | 0.13 | P |
| 58 | Maintenance Garage #3 | Exterior | Window Sash | Wood | Tan | 0.40 | P |

| Sample I.D. No. | Room/Area | | Component Description | | | Results | Paint Condition G = Good P = Peeling |
|--------------------|----------------|----------|-----------------------|-------|-------|---------|---|
| 59 | Well Pump Shed | Exterior | Siding | Wood | Tan | 0.00 | G |
| 60 | Well Pump Shed | Exterior | Soffit | Wood | Gray | 0.00 | G |
| 61 | Well Pump Shed | Exterior | Fascia | Wood | Gray | 0.00 | G |
| 62 | Well Pump Shed | Exterior | Pipe | Steel | Green | 0.00 | G |
| 63 | Calibration | | Surface | | | 1.00 | --- |
| 64 | Calibration | | Buried | | | 1.10 | --- |
| 65 | Calibration | | Surface | | | 0.90 | --- |

mg/cm² = milligrams of lead per square centimeter of paint

Appendix D

Bulk Asbestos Laboratory Report and Chain of Custody Record



EMSL Analytical, Inc.

14375 23rd Avenue North Minneapolis, MN 55447

Tel/Fax: (763) 449-4922 / (763) 449-4924

<http://www.EMSL.com / minneapolislab@emsl.com>

EMSL Order: 351902938

Customer ID: BRAU50

Customer PO: B1903316

Project ID:

Attention: Jerry Wallerius

Braun Intertec

11001 Hampshire Avenue South

Bloomington, MN 55438

Phone: (952) 995-2478

Fax: (952) 995-2020

Received Date: 05/02/2019 3:03 PM

Analysis Date: 05/06/2019 - 05/07/2019

Collected Date: 05/02/2019

Project: B1903316

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|-------------------------------------|---|--------------------------------------|--------------------------------|---|---------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 1-Sheetrock 351902938-0001 | LOWER LEVEL- MECHANICAL ROOM - SHEETROCK/ JOINT COMPOUND | Brown/Gray Fibrous Homogeneous | 15% Cellulose 2% Glass | 40% Gypsum 43% Non-fibrous (Other) | None Detected |
| 1-Joint Compound 351902938-0001A | LOWER LEVEL- MECHANICAL ROOM - SHEETROCK/ JOINT COMPOUND | White Non-Fibrous Homogeneous | | 70% Ca Carbonate 30% Non-fibrous (Other) | None Detected |
| 2 351902938-0002 | LOWER LEVEL- MECHANICAL ROOM - FURNACE TAPE(BLACK TARRY) | Black Fibrous Homogeneous | <1% Cellulose | 100% Non-fibrous (Other) | None Detected |
| 3 351902938-0003 | LOWER LEVEL- HALLWAY - CARPET ADHESIVE (TAN) | Tan Fibrous Homogeneous | 2% Cellulose <1% Synthetic | 98% Non-fibrous (Other) | None Detected |
| 4 351902938-0004 | LOWER LEVEL- CONFERENCE ROOM - 2' X 2' CEILING PANELS- TEXTURED | Gray/White Fibrous Homogeneous | 30% Cellulose 40% Min. Wool | 15% Perlite 15% Non-fibrous (Other) | None Detected |
| 5 351902938-0005 | LOWER LEVEL- SWING ROOM - 2' X 2' CEILING PANELS- FISSURED | Gray/White Fibrous Homogeneous | 30% Cellulose 40% Min. Wool | 15% Perlite 15% Non-fibrous (Other) | None Detected |
| 6 351902938-0006 | LOWER LEVEL- SWING ROOM - VINYL BASE (BEIGE) WITH ADHESIVE (TAN) | Beige Non-Fibrous Homogeneous | <1% Cellulose | 100% Non-fibrous (Other) | None Detected |
| 7 351902938-0007 | LOWER LEVEL- CLUB ROOM - FIRE STOP CAULKING (RED) | Red Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 8-Floor Tile 351902938-0008 | LOWER LEVEL- CLUB ROOM - 12" X 12" FLOOR TILE (TAN) WITH ADHESIVE (TAN) | Tan Non-Fibrous Homogeneous | | 40% Ca Carbonate 60% Non-fibrous (Other) | None Detected |
| 8-Mastic 351902938-0008A | LOWER LEVEL- CLUB ROOM - 12" X 12" FLOOR TILE (TAN) WITH ADHESIVE (TAN) | Tan Fibrous Homogeneous | 2% Cellulose | 5% Mica 93% Non-fibrous (Other) | None Detected |
| 9 351902938-0009 | LOWER LEVEL- BEVERAGE STATION - PLASTIC WALL PANEL ADHESIVE (TAN) | Tan Non-Fibrous Homogeneous | <1% Cellulose | 100% Non-fibrous (Other) | None Detected |

Initial report from: 05/07/2019 11:46:07



EMSL Analytical, Inc.

14375 23rd Avenue North Minneapolis, MN 55447

Tel/Fax: (763) 449-4922 / (763) 449-4924

<http://www.EMSL.com / minneapolislab@emsl.com>

EMSL Order: 351902938

Customer ID: BRAU50

Customer PO: B1903316

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|-----------------------------------|---|--|---------------------------|---|---------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 10 351902938-0010 | LOWER LEVEL-BEVERAGE STATION - 2' X 2' CEILING PANEL-SHEETROCK | Brown/White Fibrous Homogeneous | 20% Cellulose | 40% Gypsum 40% Non-fibrous (Other) | None Detected |
| 11-Ceramic Tile 351902938-0011 | LOWER LEVEL-BEVERAGE STATION - 4" X 4" CERAMIC FLOOR TILE (BROWN) WITH GROUT AND ADHESIVE (TAN) AND BEDDING | Brown Non-Fibrous Homogeneous | | 75% Ca Carbonate 25% Non-fibrous (Other) | None Detected |
| 11-Grout 351902938-0011A | LOWER LEVEL-BEVERAGE STATION - 4" X 4" CERAMIC FLOOR TILE (BROWN) WITH GROUT AND ADHESIVE (TAN) AND BEDDING | Gray Non-Fibrous Homogeneous | | 20% Quartz 40% Ca Carbonate 40% Non-fibrous (Other) | None Detected |
| 11-Adhesive 351902938-0011B | LOWER LEVEL-BEVERAGE STATION - 4" X 4" CERAMIC FLOOR TILE (BROWN) WITH GROUT AND ADHESIVE (TAN) AND BEDDING | Tan/White Non-Fibrous Homogeneous | <1% Cellulose | 100% Non-fibrous (Other) | None Detected |
| 11-Bedding 351902938-0011C | LOWER LEVEL-BEVERAGE STATION - 4" X 4" CERAMIC FLOOR TILE (BROWN) WITH GROUT AND ADHESIVE (TAN) AND BEDDING | Gray Non-Fibrous Homogeneous | | 10% Quartz 55% Ca Carbonate 35% Non-fibrous (Other) | None Detected |
| 12 351902938-0012 | UPPER LEVEL-KITCHEN - 2' X 4' CEILING PANEL-SHEETROCK | Brown/Gray Fibrous Homogeneous | 20% Cellulose 5% Glass | 30% Gypsum 45% Non-fibrous (Other) | None Detected |
| 13 351902938-0013 | UPPER LEVEL- BAR - 12" X 12" CERAMIC FLOOR TILE (BROWN/GRAY) WITH GROUT | Silver Non-Fibrous Homogeneous | | 85% Micaceous Flakes 15% Non-fibrous (Other) | None Detected |
| 14-Adhesive 351902938-0014 | UPPER LEVEL-MAIN DINING - CARPET ADHESIVE (TAN) WITH FLOOR LEVELER (GRAY) | Yellow Fibrous Homogeneous | 2% Cellulose | 98% Non-fibrous (Other) | None Detected |
| 14-Leveler 351902938-0014A | UPPER LEVEL-MAIN DINING - CARPET ADHESIVE (TAN) WITH FLOOR LEVELER (GRAY) | Gray Fibrous Homogeneous | 3% Cellulose | 97% Non-fibrous (Other) | None Detected |
| 15-Sheetrock 351902938-0015 | UPPER LEVEL-JANITORS CLOSET - SHEETROCK / JOINT COMPOUND | Brown/Gray/Red Fibrous Homogeneous | 20% Cellulose | 40% Gypsum 40% Non-fibrous (Other) | None Detected |

Initial report from: 05/07/2019 11:46:07



EMSL Analytical, Inc.

14375 23rd Avenue North Minneapolis, MN 55447

Tel/Fax: (763) 449-4922 / (763) 449-4924

<http://www.EMSL.com / minneapolislab@emsl.com>

EMSL Order: 351902938

Customer ID: BRAU50

Customer PO: B1903316

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|--------------------------------------|--|--|---------------|---|---------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 15-Joint Compound 351902938-0015A | UPPER LEVEL- JANITORS CLOSET - SHEETROCK / JOINT COMPOUND | White Non-Fibrous Homogeneous | <1% Cellulose | 60% Ca Carbonate 40% Non-fibrous (Other) | None Detected |
| 16 351902938-0016 | EXTERIOR- FRONT NORTH - CAULKING (TAN) ON SIDING | Tan Non-Fibrous Homogeneous | | 20% Ca Carbonate 80% Non-fibrous (Other) | None Detected |
| 17 351902938-0017 | EXTERIOR- FRONT NORTH - CAULKING (BLACK) ON DOORS AND WINDOW FRAMES | Black Non-Fibrous Homogeneous | | 20% Ca Carbonate 80% Non-fibrous (Other) | None Detected |
| 18 351902938-0018 | EXTERIOR- FRONT NORTH - CAULKING (GRAY) ON COPPER LEDGE | Silver Non-Fibrous Homogeneous | 2% Cellulose | 98% Non-fibrous (Other) | None Detected |
| 19 351902938-0019 | POOL HOUSE- EXTERIOR - ASPHALT SHINGLES (GRAY) WITH TAR PAPER | Black Fibrous Homogeneous | 55% Cellulose | 10% Quartz 35% Non-fibrous (Other) | None Detected |
| 20 351902938-0020 | POOL HOUSE- EXTERIOR - CAULKING (GRAY) ON DOOR FRAME | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 21 351902938-0021 | POOL HOUSE- EXTERIOR - POOL DECK SEALANT (GRAY) | Gray Non-Fibrous Homogeneous | <1% Cellulose | 20% Ca Carbonate 80% Non-fibrous (Other) | None Detected |
| 22-Shingle 351902938-0022 | NW PARKING LOT GARAGE- EXTERIOR - ASPHALT SHINGLES (GRAY, RED, GREEN) WITH TAR PAPER | Gray/Red/Black Fibrous Homogeneous | 55% Cellulose | 10% Quartz 35% Non-fibrous (Other) | None Detected |
| 22-Tar Paper 351902938-0022A | NW PARKING LOT GARAGE- EXTERIOR - ASPHALT SHINGLES (GRAY, RED, GREEN) WITH TAR PAPER | White/Black Fibrous Homogeneous | 60% Cellulose | 40% Non-fibrous (Other) | None Detected |
| 23 351902938-0023 | NW PARKING LOT GARAGE- EXTERIOR - CAULKING (WHITE) ON GARAGE DOOR FRAME | White Non-Fibrous Homogeneous | | 20% Ca Carbonate 80% Non-fibrous (Other) | None Detected |
| 24 351902938-0024 | WEST STORAGE- EXTERIOR - CELLULOSE BOARD | Brown Fibrous Homogeneous | 85% Cellulose | 15% Non-fibrous (Other) | None Detected |
| 25 351902938-0025 | DEBRIS PILE - 2' X 4' CEILING PANEL- FISSURED | Gray/White Fibrous Homogeneous | 75% Min. Wool | 23% Non-fibrous (Other) | 2% Chrysotile |
| 26 351902938-0026 | DEBRIS PILE - SHEETROCK | Brown/Gray Fibrous Homogeneous | 20% Cellulose | 40% Gypsum 40% Non-fibrous (Other) | None Detected |

Initial report from: 05/07/2019 11:46:07



EMSL Analytical, Inc.

14375 23rd Avenue North Minneapolis, MN 55447

Tel/Fax: (763) 449-4922 / (763) 449-4924

<http://www.EMSL.com / minneapolislab@emsl.com>

EMSL Order: 351902938

Customer ID: BRAU50

Customer PO: B1903316

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|--------------------------------------|--|-----------------------------------|----------------------------------|---|----------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 27-Sheetrock 351902938-0027 | 1475 MAINTENANCE BUILDING- INTERIOR - SHEETROCK/ JOINT COMPOUND | Brown/Gray Fibrous Homogeneous | 20% Cellulose | 40% Gypsum 40% Non-fibrous (Other) | None Detected |
| 27-Joint Compound 351902938-0027A | 1475 MAINTENANCE BUILDING- INTERIOR - SHEETROCK/ JOINT COMPOUND | White Fibrous Homogeneous | 2% Cellulose | 98% Non-fibrous (Other) | None Detected |
| 28 351902938-0028 | 1475 MAINTENANCE BUILDING- INTERIOR - 2' X 2' CEILING PANEL- PITTED | Gray/White Fibrous Homogeneous | 30% Cellulose 40% Min. Wool | 15% Perlite 15% Non-fibrous (Other) | None Detected |
| 29 351902938-0029 | 1475 MAINTENANCE BUILDING- INTERIOR - 12" X 12" CEILING TILE- FISSURES | Brown/White Fibrous Homogeneous | 85% Cellulose | 15% Non-fibrous (Other) | None Detected |
| 30-Floor Tile 351902938-0030 | 1475 MAINTENANCE BUILDING- INTERIOR - 12" X 12" FLOOR TILE (BROWN) WITH MASTIC (BLACK) | Brown Fibrous Homogeneous | <1% Cellulose 5% Wollastonite | 20% Ca Carbonate 75% Non-fibrous (Other) | <1% Chrysotile |
| 30-Mastic 351902938-0030A | 1475 MAINTENANCE BUILDING- INTERIOR - 12" X 12" FLOOR TILE (BROWN) WITH MASTIC (BLACK) | Black Fibrous Homogeneous | 2% Cellulose | 98% Non-fibrous (Other) | None Detected |
| 31 351902938-0031 | 1475 MAINTENANCE BUILDING- INTERIOR - WALL PANEL ADHESIVE (TAN) | Tan/White Non-Fibrous Homogeneous | <1% Cellulose | 100% Non-fibrous (Other) | None Detected |
| 32 351902938-0032 | 1475 MAINTENANCE BUILDING- INTERIOR - GASKET (GREEN) | Green Fibrous Homogeneous | 45% Cellulose | 55% Non-fibrous (Other) | None Detected |
| 33 351902938-0033 | 1475 MAINTENANCE BUILDING- INTERIOR - GASKET (WHITE) | Green Fibrous Homogeneous | 30% Cellulose 5% Wollastonite | 65% Non-fibrous (Other) | None Detected |
| 34 351902938-0034 | HAZMAT STORAGE- ROOF - ASPHALT SHINGLES (BLACK) WITH TAR PAPER | Black Fibrous Homogeneous | 20% Glass | 10% Quartz 20% Ca Carbonate 50% Non-fibrous (Other) | None Detected |
| Tar paper not present in sample. | | | | | |
| 35 351902938-0035 | MAINTENANCE BUILDING #2- ROOF - ASPHALT SHINGLES (GRAY) WITH TAR PAPER | Black Fibrous Homogeneous | 20% Glass | 40% Ca Carbonate 40% Non-fibrous (Other) | None Detected |
| 36 351902938-0036 | MAINTENANCE BUILDING #2- EXTERIOR - WALL ADHESIVE PUCKS (TAN) | Tan Non-Fibrous Homogeneous | <1% Cellulose | 100% Non-fibrous (Other) | None Detected |

Initial report from: 05/07/2019 11:46:07



EMSL Analytical, Inc.

14375 23rd Avenue North Minneapolis, MN 55447

Tel/Fax: (763) 449-4922 / (763) 449-4924

<http://www.EMSL.com / minneapolislab@emsl.com>

EMSL Order: 351902938

Customer ID: BRAU50

Customer PO: B1903316

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|---------------------------------|---|---------------------------------------|----------------------------------|---|----------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 37 351902938-0037 | MAINTENANCE BUILDING #2- INTERIOR - SHEETROCK | Brown/White Fibrous Homogeneous | 20% Cellulose 5% Glass | 40% Gypsum 35% Non-fibrous (Other) | None Detected |
| 38 351902938-0038 | MAINTENANCE BUILDING #2- INTERIOR - CELLULOSE BOARD | Black Fibrous Homogeneous | 20% Cellulose | 80% Non-fibrous (Other) | None Detected |
| 39 351902938-0039 | MAINTENANCE GARAGE #3- INTERIOR - TRANSITE (GRAY) | Gray Fibrous Homogeneous | | 45% Ca Carbonate 30% Non-fibrous (Other) | 25% Chrysotile |
| 40 351902938-0040 | MAINTENANCE GARAGE #3- INTERIOR - CELLULOSE BOARD | Brown Fibrous Homogeneous | 85% Cellulose | 15% Non-fibrous (Other) | None Detected |
| 41 351902938-0041 | WELL PUMP SHED- EXTERIOR - 12" PIPE GASKET (WHITE) | White Fibrous Homogeneous | 45% Cellulose 5% Wollastonite | 50% Non-fibrous (Other) | None Detected |
| 42-Shingle 351902938-0042 | WELL PUMP SHED- EXTERIOR - ASPHALT SHINGLES (GRAY) WITH TAR PAPER | Black Fibrous Homogeneous | 20% Glass | 10% Quartz 20% Ca Carbonate 50% Non-fibrous (Other) | None Detected |
| 42-Tar Paper 351902938-0042A | WELL PUMP SHED- EXTERIOR - ASPHALT SHINGLES (GRAY) WITH TAR PAPER | Black Fibrous Homogeneous | 75% Cellulose | 25% Non-fibrous (Other) | None Detected |

Analyst(s)

Joshua Moorman (50)

Kelly Gallisdorfer (3)

Rachel Travis, Laboratory Manager
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method"), but augmented with procedures outlined in the 1993 ("final") version of the method. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. All samples received in acceptable condition unless otherwise noted. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. EMSL recommends gravimetric reduction for all non-friable organically bound materials prior to analysis. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc. Morrisville, NC NVLAP Lab Code 200671-0, VA 3333 000278, WVA LT000296

Initial report from: 05/07/2019 11:46:07



EMSL Analytical, Inc.

14375 23rd Avenue North Minneapolis, MN 55447

Phone/Fax: (763) 449-4922 / (763) 449-4924

<http://www.EMSL.com> / minneapolislab@emsl.com

EMSL Order: 351902938

Customer ID: BRAU50

Customer PO: B1903316

Project ID:

Attention: Jerry Wallerius
Braun Intertec
11001 Hampshire Avenue South
Bloomington, MN 55438

Phone: (952) 995-2478
Fax: (952) 995-2020
Received: 05/02/2019 3:03 PM
Analysis Date: 05/07/2019 - 05/10/2019
Collected: 05/02/2019

Project: B1903316

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy. Quantitation using 400 Point Count Procedure

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|---------------------------------|--|--------------------------------------|--------------|---------------------------|------------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 25 351902938-0025 | DEBRIS PILE - 2' X 4' CEILING PANEL- FISSURED | Gray/White Fibrous Homogeneous | | 95.8% Non-fibrous (Other) | 4.25% Chrysotile |
| 30-Floor Tile 351902938-0030 | 1475 MAINTENANCE BUILDING- INTERIOR - 12" X 12" FLOOR TILE (BROWN) WITH MASTIC (BLACK) | Brown Non-Fibrous Homogeneous | | 98.8% Non-fibrous (Other) | 1.25% Chrysotile |

Point Count performed on NOB material without gravimetric reduction at client request. Asbestos results may be under-reported.

Analyst(s)

Joshua Moorman (1)

Roxsee Stover (1)

Rachel Travis, Laboratory Manager
or other approved signatory

Disclaimer: Some samples may contain asbestos fibers present in dimensions below PLM resolution limits. The limit of detection as stated in the method is 0.25%. EMSL Analytical Inc suggests that samples reported as <0.25% or none detected undergo additional analysis via TEM. The above test report relates only to the items tested. This report may not be reproduced, except in full, without written approval of EMSL Analytical Inc. This test report must not be used by the client to claim product endorsement by NVLAP or any agency of the United States Government. EMSL Analytical Inc., bears no responsibility for sample collection activities, analytical method limitations, or the accuracy of results when requested to separate layered samples. EMSL Analytical Inc., liability is limited to the cost of sample analysis. The test results contained within this report meet the requirements of NELAC unless otherwise noted. Samples received in good condition unless otherwise noted. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample.

Samples analyzed by EMSL Analytical, Inc. Morrisville, NC NVLAP Lab Code 200671-0, VA 3333 000278, WVA LT000296

Report amended: 05/16/2019 10:59:34 Replaces initial report from: 05/07/2019 11:46:13 Reason Code: Client-Additional Analysis



EMSL Analytical, Inc.

14375 23rd Avenue North Minneapolis, MN 55447

Phone/Fax: (763) 449-4922 / (763) 449-4924

<http://www.EMSL.com> / minneapolislab@emsl.com

EMSL Order: 351902938

Customer ID: BRAU50

Customer PO: B1903316

Project ID:

Attention: Jerry Wallerius
Braun Intertec
11001 Hampshire Avenue South
Bloomington, MN 55438

Phone: (952) 995-2478
Fax: (952) 995-2020
Received: 05/02/2019 3:03 PM
Analysis Date: 05/07/2019
Collected: 05/02/2019

Project: B1903316

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy. Quantitation using 400 Point Count Procedure

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|---------------------------------|--|-------------------------------------|--------------|---------------------------|------------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 30-Floor Tile 351902938-0030 | 1475 MAINTENANCE BUILDING- INTERIOR - 12" X 12" FLOOR TILE (BROWN) WITH MASTIC (BLACK) | Brown Non-Fibrous Homogeneous | | 98.8% Non-fibrous (Other) | 1.25% Chrysotile |

Point Count performed on NOB material without gravimetric reduction at client request. Asbestos results may be under-reported.

Analyst(s)

Joshua Moorman (1)

Rachel Travis, Laboratory Manager
or other approved signatory

Disclaimer: Some samples may contain asbestos fibers present in dimensions below PLM resolution limits. The limit of detection as stated in the method is 0.25%. EMSL Analytical Inc suggests that samples reported as <0.25% or none detected undergo additional analysis via TEM. The above test report relates only to the items tested. This report may not be reproduced, except in full, without written approval of EMSL Analytical Inc. This test report must not be used by the client to claim product endorsement by NVLAP or any agency of the United States Government. EMSL Analytical Inc., bears no responsibility for sample collection activities, analytical method limitations, or the accuracy of results when requested to separate layered samples. EMSL Analytical Inc., liability is limited to the cost of sample analysis. The test results contained within this report meet the requirements of NELAC unless otherwise noted. Samples received in good condition unless otherwise noted. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample.

Samples analyzed by EMSL Analytical, Inc. Morrisville, NC NVLAP Lab Code 200671-0, VA 3333 000278, WVA LT000296

Initial report from: 05/07/2019 11:46:05

EMSL ANALYTICAL, INC.
LABORATORY • PRODUCTS • TRAINING

Asbestos Chain of Custody

EMSL Order Number (Lab Use Only):

2938

EMSL ANALYTICAL, INC
14375 23RD AVE. NORTH
MINNEAPOLIS, MN 55447PHONE: (763) 449-4922
FAX: (763) 449-4924

| | | | |
|---|--------------------------------------|---|---------------------------|
| Company Name: <u>BRAUN INTERTEC</u> | | EMSL Customer ID: | |
| Street: <u>11001 HAMPSHIRE AVE S.</u> | | City: <u>BLOOMINGTON</u> | State/Province: <u>MN</u> |
| Zip/Postal Code: <u>55438</u> | Country: <u>U.S.A.</u> | Telephone #: <u>612-360-6733</u> | Fax #: |
| Report To (Name): <u>JERRY WALLACE</u> | | Please Provide Results: <input type="checkbox"/> Fax <input checked="" type="checkbox"/> Email | |
| Email Address: <u>JWALLACE@BRAUNINTERTEC.COM</u> | | Purchase Order: | |
| Project Name/Number: <u>BL903316</u> | | EMSL Project ID (Internal Use Only): | |
| U.S. State Samples Taken: <u>MINNESOTA</u> | | CT Samples: <input type="checkbox"/> Commercial/Taxable <input type="checkbox"/> Residential/Tax Exempt | |
| EMSL-Bill to: <input checked="" type="checkbox"/> Same <input type="checkbox"/> Different - If Bill to is Different note instructions in Comments** Third Party Billing requires written authorization from third party | | | |
| Turnaround Time (TAT) Options* - Please Check | | | |
| <input type="checkbox"/> 3 Hour <input type="checkbox"/> 6 Hour <input type="checkbox"/> 24 Hour <input type="checkbox"/> 48 Hour <input checked="" type="checkbox"/> 72 Hour <input type="checkbox"/> 96 Hour <input type="checkbox"/> 1 Week <input type="checkbox"/> 2 Week | | | |
| *For TEM Air 3 hr through 6 hr, please call ahead to schedule. *There is a premium charge for 3 Hour TEM AHERA or EPA Level II TAT. You will be asked to sign an authorization form for this service. Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide. | | | |
| PCM - Air <input type="checkbox"/> Check if samples are from NY <input type="checkbox"/> NIOSH 7400 <input type="checkbox"/> w/ OSHA 8hr. TWA | | TEM - Air <input type="checkbox"/> 4-4.5hr TAT (AHERA only) <input type="checkbox"/> AHERA 40 CFR, Part 763 <input type="checkbox"/> NIOSH 7402 <input type="checkbox"/> EPA Level II <input type="checkbox"/> ISO 10312 | |
| PLM - Bulk (reporting limit) <input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%) <input type="checkbox"/> PLM EPA NOB (<1%) Point Count <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) Point Count w/Gravimetric <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) <input type="checkbox"/> NYS 198.1 (friable in NY) <input type="checkbox"/> NYS 198.6 NOB (non-friable-NY) <input type="checkbox"/> NYS 198.8 SOF-V <input type="checkbox"/> NIOSH 9002 (<1%) | | TEM - Bulk <input type="checkbox"/> TEM EPA NOB <input type="checkbox"/> NYS NOB 198.4 (non-friable-NY) <input type="checkbox"/> Chatfield SOP <input type="checkbox"/> TEM Mass Analysis-EPA 600 sec. 2.5 TEM - Water: EPA 100.2 Fibers >10µm <input type="checkbox"/> Waste <input type="checkbox"/> Drinking All Fiber Sizes <input type="checkbox"/> Waste <input type="checkbox"/> Drinking | |
| TEM - Dust <input type="checkbox"/> Microvac - ASTM D 5755 <input type="checkbox"/> Wipe - ASTM D6480 <input type="checkbox"/> Carpet Sonication (EPA 600/J-93/167) | | Soil/Rock/Vermiculite <input type="checkbox"/> PLM EPA 600/R-93/116 with milling prep (<1%) <input type="checkbox"/> PLM EPA 600/R-93/116 with milling prep (<0.25%) <input type="checkbox"/> TEM EPA 600/R-93/116 with milling prep (<0.1%) <input type="checkbox"/> TEM Qualitative via Filtration Prep <input type="checkbox"/> TEM Qualitative via Drop Mount Prep <input type="checkbox"/> Cincinnati Method EPA 600/R-04/004 - PLM/TEM (BC only) | |
| <input type="checkbox"/> Check For Positive Stop - Clearly Identify Homogenous Group | | Filter Pore Size (Air Samples): <input type="checkbox"/> 0.8µm <input type="checkbox"/> 0.45µm | |
| Samplers Name: <u>JERRY WALLACE</u> <u>STEVE LUTCH</u> | | Samplers Signature: <u>[Signature]</u> | |
| Sample # | Sample Description | Volume/Area (Air) HA # (Bulk) | Date/Time Sampled |
| 1 → 42 | 2200 LAPEL AVE, E. "SEE TABLE II" | Bulk | 5-2-19 |
| | | | |
| | | | |
| | | | |
| | | | |
| Client Sample # (s): <u>1 THROUGH 42</u> | | Total # of Samples: <u>42</u> | |
| Relinquished (Client): <u>[Signature]</u> | Date: <u>5-2-2019</u> | Time: <u>3:03 pm</u> | |
| Received (Lab): <u>Alindahl W</u> | Date: <u>5-2-19</u> | Time: <u>3:03 pm</u> | |
| Comments/Special Instructions: <u>PLEASE POINT COUNT IF 1% OR LESS</u> | | | |

BRAUN**INTERTEC****Table II. Bulk Asbestos Analytical Results**

• Providing engineering and environmental solutions since 1957

Client:

Location: 2200 CARPENTERS AVE. E, ST. PAUL, MN

Date of Inspection 5-2-2019

Project No.: B1903316

| Sample No. | Sample Location | Material | Asbestos Content (%) ¹ |
|------------|-------------------------------|--|-----------------------------------|
| 1 | LOWER LEVEL - MECHANICAL ROOM | SHEETROCK JOINT COMPOUND | |
| 2 | ↓ - ↓ | FURNACE TAPE (BLACK TAMP) | |
| 3 | ↓ - HALLWAY | CARPET ADHESIVE (TAN) | |
| 4 | ↓ - CONFERENCE ROOM | 2'x2' CEILING PANELS - TEXTURED | |
| 5 | ↓ - SWIMMING ROOM | 2'x2' CEILING PANELS - TEXTURED | |
| 6 | ↓ - ↓ | VINYL BASE (BEIGE) WITH ADHESIVE (TAN) | |
| 7 | ↓ - CLUB ROOM | FIRE STOP CAULKING (RED) | |
| 8 | ↓ - ↓ | 12" x 12" FLOOR TILE (TAN) WITH ADHESIVE (TAN) | |
| 9 | ↓ - BEVERAGE STATION | PLASTIC WALL PANEL ADHESIVE (TAN) | |
| 10 | ↓ - ↓ | 2'x2' CEILING PANEL - SHEETROCK | |
| 11 | ↓ - ↓ | 4'x4' CERAMIC FLOOR TILE (BROWN) WITH GROUT AND ADHESIVE (TAN) AND GROUT | |
| 12 | UPPER LEVEL - KITCHEN | 2'x4' CEILING PANEL - SHEETROCK | |
| 13 | ↓ - BAR | 12" x 12" CERAMIC FLOOR TILE (BROWN/GRAY) WITH GROUT | |
| 14 | ↓ - MAIN DINING | CARPET ADHESIVE (TAN) WITH FLOOR TENSILE (GRAY) | |
| 15 | ↓ - JANITORS CLOSET | SHEETROCK JOINT COMPOUND | |
| 16 | EXTERIOR - FRONT PORCH | CAULKING (TAN) ON SILLING | |
| 17 | ↓ - ↓ | CAULKING (BLACK) ON DOORS AND WINDOW FRAMES | |
| 18 | ↓ - ↓ | CAULKING (GRAY) ON COPPER LEADS | |
| 19 | POOL HOUSE - EXTERIOR | ASPHALT SHINGLES (GRAY) WITH TAR PAPER | |
| 20 | ↓ - ↓ | CAULKING (GRAY) ON DOOR FRAME | |
| 21 | ↓ - ↓ | POOL DECK SEALANT (GRAY) | |
| 22 | NW PARKING LOT OVERPASS - ↓ | ASPHALT SHINGLES (GRAY, RED, GREEN) WITH TAR PAPER | |
| 23 | ↓ - ↓ | CAULKING (WHITE) ON BRACE DOOR FRAME | |
| 24 | WEST STORAGE - ↓ | CELLULOSE BOARD | |
| 25 | DEBOIL PILE | 2'x4' CEILING PANEL - AC-CURSED | |
| 26 | ↓ | SHEETROCK | |

Materials containing 1 percent of asbestos or less are not considered to be asbestos-containing materials by the U.S. EPA.

1. Asbestos content is indicated as an approximate percent by area.
2. N.D. = None Detected.
3. N.A. = Not Analyzed.
4. < = Less Than.

2 of 3

2938

Table II. Bulk Asbestos Analytical Results

• *Providing engineering and environmental solutions since 1957*

Location: 2200 CARPENTERS AVE. E. ST. PAUL, MN
Date of Inspection 5-2-2018

Date of Inspection 5-2-2019

Project No.: 131903316

Materials containing 1 percent of asbestos or less are not considered to be asbestos-containing materials by the U.S. EPA.

1. Asbestos content is indicated as an approximate percent by area.
2. N.D. = None Detected.
3. N.A. = Not Analyzed.
4. < = Less Than.

3063

Appendix E

Asbestos Inspector Certificate

Certificate No: 5LM01251814IR

Expiration Date: January 25, 2019

This is to certify that

Stephen Luth

has attended and successfully completed an

**ASBESTOS INSPECTOR
REFRESHER TRAINING COURSE**

permitted by

the State of Minnesota under Minnesota Rules 4620.3702 to 4620.3722

and meets the requirements of

Section 206 of Title II of the Toxic Substances Control Act (TSCA)

conducted by

Lake States Environmental, Ltd.

White Bear Lake, MN on January 25, 2018

Examination Date: January 25, 2018

Lake States Environmental, Ltd

P. O. Box 645, Rice Lake, WI 54868

(800) 254-9811

Paul D. McNeill
Training Inspector



Director, Env. Health Div.

**m ASBESTOS
DEPARTMENT INSPECTOR
OF HEALTH**

Certified by:

State of Minnesota
Department of Health

Expires: 01/25/2019

Stephen A Luth
5893 200th St W
Farmington, MN 55024

No. A110702

Issued: 02/01/2018

Certificate No: 5LM11061803IR

Expiration Date: November 6, 2019

This is to certify that

Gerald J. Wallerius

has attended and successfully completed an

**ASBESTOS INSPECTOR
REFRESHER TRAINING COURSE**

permitted by

the State of Minnesota under Minnesota Rules 4620.3702 to 4620.3722

and meets the requirements of

Section 206 of Title II of the Toxic Substances Control Act (TSCA)

conducted by

Lake States Environmental, Ltd.

in

Hudson, WI on November 6, 2018

Examination Date: November 6, 2018

Lake States Environmental, Ltd
P. O. Box 645, Rice Lake, WI 54868
(800) 254-9811

Grant / Grasse
Training Instructor



Director, Env. Health Div.

m ASBESTOS
DEPARTMENT OF HEALTH INSPECTOR
Certified by:
State of Minnesota
Department of Health
Expires: 11/06/2019
Gerald J Wallerius
3010 Garland Ln N
Plymouth, MN 55447

No. AI2305 Issued: 11/15/2018